

ORINDA HYDRANTS WITH GROSSLY INADEQUATE FLOWS

Rev. 7-21-95

LOCATION	SPRC. COND.	BBMUD MAP PAGE	PRS ZNE	MAN SIZ	LAST TEST DAT	ST. PRS	RS1 PRS	RS2 PRS	PIT PRS	OBS. FLOW	AVBL FLOW	COLORS	HYD.No.	TYPE
Bien Venida/West Wy	→	1512B512	D7B	06	10/25/94	120	11	1	09	0500	0475	T/R C/O	#18254	M74
Cm Del Diablo, 21	→	1506B508		04	00/00/85	54	05		09	0500	0410	T/R C/O	#H11671	M64
Cm Del Diablo, 41	DRY →	1506B508		04	00/00/00	60	10		08	0480	0415	T/R C/O	#39	M22
Cm Don Miguel, 127	→	1509B512	D5A	04	10/05/94	42	05	12	04	0335	0250	T/R C/R	#16970	M74
Cm Encinas, 80	→	1515B502	D5A	04	01/17/95	98	10	28	10	0530	0495	T/R C/O	#14461	M65
Charles Hill Cir/South Point Rd	→	1518B512	D9C	04	12/01/94	131	10	12	04	0335	0315	T/R C/G	#13194	M64
Charles Hill Cir, 15	→	1518B512	D9C	04	12/01/94	150	12	NA	04	0335	0320	T/R C/G	#16717	M74
Charles Hill Cir, 25	→	1518B512		04	00/00/00	105	14		06	0410	0395	T/R C/O	#71-L	M74
Charles Hill Cir, 37	→	1518B512	D9C	04	12/01/94	53	14	20	05	0375	0340	T/R C/O	#16718	M74
Charles Hill Rd/Honey Hill Rd	→	1518B512	D7B	06	03/17/95	40	8	10	07	0440	0340	T/R C/R	#16668	M74
Charles Hill Rd #41	→	1518B514	D9C	06	12/01/94	38	06	NA	05	0355	0265	T/R C/O	#23	M64
Dolores Wy/Rita Wy	→	1521B494	D5Ac	06	00/00/91	50	08		08	0470	0390	T/R C/R	#12707	M64
Dolores Wy # 10	→	1518B494	D5Ac	06	12/30/94	55	08	18	10	0530	0450	T/R C/O	#H19258	M64
BBMUD Filter Plant/NB side	→	1509B510		04	00/00/85	142	02		05	0410	0345	T/R C/G	#H10013	M74
El Toyonal/Loma Vista (upper)	→	1506B508	D7C	06	10/25/94	45	05	25	09	0500	0385	T/R C/R	#47	M75
Heather Ln, 23	(R) →	1518B502	D5Ab	06	01/21/95	42	12	10	10	0530	0445	T/R C/R	#H11048	M64
La Cintilla, 25	(R) →	1512B514		06	00/00/85	40	05		08	0470	0345	T/R C/R	#14891	M64
La Cuesta/Cascade Ln	→	1512B510	D7B	06	10/07/94	144	10	14	05	0375	0355	T/R C/G	#21	M74
La Cuesta/Via Farallon	→	1512B510	D7B	06	10/07/94	115	05	18	04	0335	0305	T/R C/O	#10628	M75
La Cuesta #85	→	1512B510	D7B	04	10/07/94	70	16	60	08	0470	0450	T/R C/O	#37	M74
Linda Vista, 21	→	1512B510		04	00/00/85	92	06		04	0340	0300	T/R C/O	#10337	M74
Loma Vista/La Bolsita	→	1509B508	D7C	04	10/25/94	138	01	01	05	0375	0345	T/R C/G	#26	M65
Los Dedos/El Pulgar	→	1515B512	D9C	04	04/01/95	108	01	08	03	0305	0270	T/R C/O	#11442	M74
Mira Loma/El Patio/Linda Vista	(R) →	1512B508		06	00/00/85	124	12		06	0410	0390	T/R C/G	#34	M74
Oak Rd, 14	→	1512B504		06	00/00/91	40	10		10	0530	0425	T/R C/R	#H14853	M64
Patrick Ln, 4	→	1521B504	D7A	08	11/02/94	102	20	23	08	0470	0470	T/R C/O	#H16161	M64
Patrick Ln, 1	→	1521B504	D7A	08	00/00/87	92	10		08	0470	0435	T/R C/O	#H16162	M64
Ranch Rd, 18	→	1515B516		04	00/00/85	155	10		09	0500	0480	T/R C/G	#10409	M74
Sunrise Hill Rd, 22	→	1515B500	D5Ab	06	11/04/94	50	08	20	07	0440	0365	T/R C/O	#H19436	M64
Tappan Te, 315	→	1509B518		08	00/00/85	44	16		10	0530	0485	T/R C/R	#H14100	M64
Tappan Wy, 1	→	1509B518		08	00/00/85	20	07		06	0410	0355	T/R C/R	#H15816	M64
Tarabrook Rd, 18	→	1518B506		06	00/00/85	62	16		09	0500	0475	T/R C/O	#19183	M74
Vallecito Ln, 24	→	1506B508		06	00/00/00	130	15		08	0480	0455	T/R C/G	#10304	M74
Via Farallon, 12	(R) →	1512B510		06	00/00/85	82	10		08	0480	0430	T/R C/O	#18	M74
Via Hermosa, 18	→	1512B512	D7B	04	04/01/95	80	5	10	03	0305	0270	T/R C/O	#27	M74

"Grossy Inadequate" is defined as available fire flows of less than 500 GPM @ 20 psi residual or @ half the static pressure when static pressure is less than 40 psi.